

This damage is on the fascia board on the eastern side of the structure, approximately where the gutter attaches and around the chimney. This is on the attic level(third floor)





This damage is on the front fascia board, approximately where the gutter attaches. This is on the attic level(third floor).



This damage is on the fascia board on the western side of the structure, approximately where the gutter attaches. This is on the roof awning level(second level)